

The electrical distribution boxes in Guyana are too ugly

In its continued effort to tackle the sale and distribution of substandard electrical fittings and equipment, the Product Compliance Department of the Guyana National Bureau of Standards ...

Following a series of mandatory inspections, the Guyana National Bureau of Standards (GNBS) on Tuesday seized and destroyed a number of cigarettes, electrical fittings and equipment, ...

The Guyana National Bureau of Standard has seized a number of items from several business owners for improper labeling and poor quality. Among the items seized by the GNBS were ...

In a move to uphold safety standards and protect consumers, the Guyana National Bureau of Standards (GNBS) has seized and destroyed a substantial cache of substandard electrical ...

Despite billions being funneled into energy projects, grid upgrades, and new generating sets, Guyana's electrical infrastructure is as fragile as ever. It's not just the occasional blackout that ...

The Guyana National Bureau of Standards (GNBS) recently said that its Product Compliance Department seized and destroyed 11,660 pieces of substandard electrical fittings and ...

Poor reliability has been linked to dependence on old and obsolete equipment for power generation, underinvestment in the distribution grid, and lack of incentives for efficient provision of service. The ...

The Guyana National Bureau of Standard has seized a number of items from several business owners for improper labeling and poor quality. ...

The collapse of several power poles along this major roadway, plunging the area into darkness, highlights the precarious state of Guyana's power grid and underscores the disastrous ...

The electricity service provided to Guyana Power and Light (GPL) customers does not meet the reliability and quality requirements of utilities in developed countries.

The electrical distribution boxes in Guyana are too ugly

Web: <https://www.tlaletsoglobal.co.za>