

Huawei core switch cannot be pinged for access

View and Download Huawei HG8245 series quick start manual online. EchoLife Gateway GPON Terminal. HG8245 series network router pdf manual download. Also for: Hg8247 series, Hg8447 series.

View and Download Huawei HG8245 series quick start manual online. EchoLife Gateway GPON Terminal. HG8245 series network router pdf manual download. ...

Case Study: Directly Connected Devices Cannot Ping Each Other Because of an Incorrect Static ARP Entry
Case Study: A Switch Can Be Pinged But Cannot Be Remotely Accessed

This is likely related to how the vlans are setup with the gateways on the core switch, and the vlan where the mgmt interface is on the edge switch where the device is connected.

Case Study: A Device Can Be Pinged but Cannot Be Remotely Accessed Symptom In Figure 14-7, DeviceC can ping the IP address of interface 1 on DeviceA, but cannot access DeviceA ...

If the remote end can successfully ping the switch but the switch cannot ping the remote end, check whether the ping function is disabled on the remote end (for example, ping is prohibited ...

When the physical and logical fiber connections of the OPM8 board are inconsistent, the #OPM8 board cannot monitor the actual data. This case shares an effective solution, so check it out: ...

Are these in separate networks? If so, you'll need to add the routes. It would appear that the core switch just isn't sure where exactly to send the packets because routes aren't there.

Without an address, your switches cannot participate in any network layers above layer-2. Switching happens at layer-2, and unmanaged switches cannot ping or be pinged.

Case Study: An Access Switch Cannot Ping the Gateway When the Uplink and Downlink Interfaces of the Aggregation Switch Are Bundled into Eth-Trunks Respectively Translation

SwitchC can successfully ping SwitchA, indicating that the link between SwitchC and SwitchA is normal, but the route may be abnormal. Therefore, you need to check whether there is a reachable route ...

Huawei core switch cannot be pinged for access

Web: <https://www.tlaletsoglobal.co.za>