

You must Register on this Forum and validate your email address before you can post a new topic. If you want to REVIEW Your ISP then be aware that we use a separate member database and system ...

This guide provides a step-by-step process for downgrading the China Unicom VN007+ and gaining superuser (admin) access; however, please be aware that your device may still be at ...

The China Unicom 5G VN007+ CPE router faces real-world limitations, including unsafe plug adapters, sub-2.3Gbps speeds in urban areas, and unreliable mesh networking, raising concerns about its ...

Join the industry's defining body for Broadband Networks. Find out the benefits of joining and how we work.

China Telecom was caught flat-footed by its rival, China Unicom, and is now aggressively trying to catch up before Unicom siphons away additional customers with offers of free FTTR ...

Hello, I own a HTC Desire 816w which is a made of Taiwan (China Unicom). I recently updated it with some troubles and was successful in updating it, details here.

They provided amazon eero 6 plus router and I'm only getting 500 Mbs to my 6e capable devices (6 plus does not support 6e). BUT the question is... when i do speed tests (various), why is it connecting to ...

This mass-produced device has troubled internet users not just in China, but all around the world. Fortunately, giving this device a quick restart can fix -- and prevent -- most minor connection ...

I asked on their forum if they could add a feature to ignore brief LTE link interruptions and got one suggestion to use src-nat instead of masquerade in the firewall. Unfortunately, src-nat ...

I'm online again now via direct ethernet connection, so my China Unicom connection is fine but the router is having some kind of problem -- from a brief glance it looked like it wasn't getting ...

Web: <https://www.tlaetsoglobal.co.za>